

Table I—Sample size code letters

(See 9.2 and 9.3)

Lot or batch size			Special inspection levels				General inspection levels		
			S-1	S-2	S-3	S-4	I	II	III
2	to	8	A	A	A	A	A	B	
9	to	15	A	A	A	A	A	C	
16	to	25	A	A	B	B	B	D	
26	to	50	A	B	B	C	C	E	
51	to	90	B	B	C	C	C	F	
91	to	150	B	B	C	D	D	G	
151	to	280	B	C	D	E	E	H	
281	to	500	B	C	D	E	F	J	
501	to	1200	C	C	E	F	G	K	
1201	to	3200	C	D	E	G	H	L	
3201	to	10000	C	D	F	G	J	M	
10001	to	35000	C	D	F	H	K	N	
35001	to	150000	D	E	G	J	L	P	
150001	to	500000	D	E	G	J	M	Q	
500001	and over		D	E	H	K	N	R	

Table II-A—Single sampling plans for normal inspection (Master table)

(See 9.4 and 9.5)

Sample size code letter	Sample size	Acceptance Quality Limits, AQLs, in Percent Nonconforming Items and Nonconformities per 100 Items (Normal Inspection)																											
		0.010	0.015	0.025	0.040	0.065	0.10	0.15	0.25	0.40	0.65	1.0	1.5	2.5	4.0	6.5	10	15	25	40	65	100	150	250	400	650	1000		
		Ac Re	Ac Re	Ac Re	Ac Re	Ac Re	Ac Re	Ac Re	Ac Re	Ac Re	Ac Re	Ac Re	Ac Re	Ac Re	Ac Re	Ac Re	Ac Re	Ac Re	Ac Re	Ac Re	Ac Re	Ac Re	Ac Re	Ac Re	Ac Re	Ac Re	Ac Re	Ac Re	
A	2	↓	↓	↓	↓	↓	↓	↓	↓	↓	↓	↓	↓	↓	↓	0 1	↓	↓	1 2	2 3	3 4	5 6	7 8	10 11	14 15	21 22	30 31		
B	3	↓	↓	↓	↓	↓	↓	↓	↓	↓	↓	↓	↓	↓	↓	0 1	↕	↓	1 2	2 3	3 4	5 6	7 8	10 11	14 15	21 22	30 31	44 45	
C	5	↓	↓	↓	↓	↓	↓	↓	↓	↓	↓	↓	↓	↓	0 1	↕	↕	1 2	2 3	3 4	5 6	7 8	10 11	14 15	21 22	30 31	44 45	↑	
D	8	↓	↓	↓	↓	↓	↓	↓	↓	↓	↓	↓	0	↕	↓	1 2	2 3	3 4	5 6	7 8	10 11	14 15	21 22	30 31	44 45	↑	↑	↑	
E	13	↓	↓	↓	↓	↓	↓	↓	↓	↓	↓	0 1	↕	↓	1 2	2 3	3 4	5 6	7 8	10 11	14 15	21 22	30 31	44 45	↑	↑	↑	↑	
F	20	↓	↓	↓	↓	↓	↓	↓	↓	↓	↓	0 1	↕	1 2	2 3	3 4	5 6	7 8	10 11	14 15	21 22	↑	↑	↑	↑	↑	↑	↑	
G	32	↓	↓	↓	↓	↓	↓	↓	↓	↓	0 1	↕	1	2 3	3 4	5 6	7 8	10 11	14 15	21 22	↑	↑	↑	↑	↑	↑	↑	↑	
H	50	↓	↓	↓	↓	↓	↓	↓	↓	↓	0 1	↕	1	2 3	3 4	5 6	7 8	10 11	14 15	21 22	↑	↑	↑	↑	↑	↑	↑	↑	
J	80	↓	↓	↓	↓	↓	↓	↓	↓	↓	0 1	↕	1	2 3	3 4	5 6	7 8	10 11	14 15	21 22	↑	↑	↑	↑	↑	↑	↑	↑	
K	125	↓	↓	↓	↓	↓	↓	↓	↓	↓	0 1	↕	1 2	2 3	3 4	5	7 8	0 11	14 15	21 22	↑	↑	↑	↑	↑	↑	↑	↑	
L	200	↓	↓	↓	↓	0 1	↕	1 2	2 3	3 4	5 6	7	10 11	14 15	21 22	↑	↑	↑	↑	↑	↑	↑	↑	↑	↑	↑	↑	↑	
M	315	↓	↓	0 1	↕	1 2	2 3	3 4	5 6	7 8	10 11	14 15	21 22	↑	↑	↑	↑	↑	↑	↑	↑	↑	↑	↑	↑	↑	↑	↑	
N	500	↓	↓	0 1	↕	1 2	2 3	3 4	5 6	7 8	10 11	14 15	21 22	↑	↑	↑	↑	↑	↑	↑	↑	↑	↑	↑	↑	↑	↑	↑	
P	800	↓	0 1	↕	1 2	2 3	3 4	5 6	7 8	10 11	14 15	21 22	↑	↑	↑	↑	↑	↑	↑	↑	↑	↑	↑	↑	↑	↑	↑	↑	
Q	1250	0 1	↑	↕	1 2	2 3	3 4	5 6	7 8	10 11	14 15	21 22	↑	↑	↑	↑	↑	↑	↑	↑	↑	↑	↑	↑	↑	↑	↑	↑	
R	2000	↑	↑	1 2	2 3	3 4	5 6	7 8	10 11	14 15	21 22	↑	↑	↑	↑	↑	↑	↑	↑	↑	↑	↑	↑	↑	↑	↑	↑	↑	

↓ = Use the first sampling plan below the arrow. If sample size equals, or exceeds, lot size, carry out 100 percent inspection.

↑ = Use the first sampling plan above the arrow.

Ac = Acceptance number.

Re = Rejection number.